

Customer Update XCU2001-02

XC17V16 and XC17V08 One-Time Programmable PROM Devices

Subject: New Xilinx HW-130 Programmer Adapter for the XC17V16 and XC17V08 PROM Devices

Description: Xilinx has manufactured a new socket adapter for the XC17V16 and XC17V08 one-time programmable PROM devices for programming on the Xilinx HW-130 Programmer. Customers using the Xilinx HW-130 Programmer to program the XC17V16 and XC17V08 PROM devices need to order the new HW-137-PC44/VQ44 socket adapter. The ordering part number for this new socket adapter is HW-137-PC44/VQ44 and can be ordered now. Both the XC17V16 and XC17V08 PROM devices will require this new socket adapter in order to program on the Xilinx HW-130 Programmer due to the need for an additional programming pin.

Customers will also need to update their HW-130 Programmer software to version 4.93 (02/07/2001) available from the Xilinx ftp site at:
<ftp://ftp.xilinx.com/pub/swhelp/programmer/hw130w32.exe>.

The HW-137-PC44/VQ44 socket adapter can also be used to program other Xilinx 44-pin PLCC and 44-pin VQFP devices on the HW-130 Programmer, but it is not required. For a complete list of socket adapters and devices supported by the HW-130 Programmer please visit <http://www.xilinx.com/support/programr/adapters.htm>.

This change *does not* affect third party programmer manufacturers.

Products Affected

XC17V16PC44C	XC17V08PC44C
XC17V16PC44I	XC17V08PC44I
XC17V16VQ44C	XC17V08VQ44C
XC17V16VQ44I	XC17V08VQ44I

Key Dates

The HW-137-PC44/VQ44 socket adapter is available to order now.

Response

No response to this notification is required. If you have any questions regarding this advisory, please contact your local Xilinx Sales Representative.