

# PCN00002A Data

## Cross-Reference List for PCN00002A

| Philips Part Numbers and Assy Info |               |          | Xilinx Part Numbers and Assy Info |                       |                         |         |
|------------------------------------|---------------|----------|-----------------------------------|-----------------------|-------------------------|---------|
| Part No                            | Assy Location | Drawing  | Part No                           | Primary Assy Location | Secondary Assy Location | Drawing |
| P3Z22V10-BA                        | Korea         | SOT261-3 | XCR22LV10-15PC28C                 | Philippines           |                         | OPC0001 |
| P3Z22V10-BD                        | Thailand      | SOT137-1 | XCR22LV10-15SO24C                 | Korea                 | Philippines             | OPD0010 |
| P3Z22V10-BDH                       | Thailand      | SOT355-1 | XCR22LV10-15VO24C                 | Korea                 | Philippines             | OPD0011 |
| P3Z22V10-DA                        | Korea         | SOT261-3 | XCR22LV10-10PC28C                 | Philippines           |                         | OPC0001 |
| P3Z22V10-DD                        | Thailand      | SOT137-1 | XCR22LV10-10SO24C                 | Korea                 | Philippines             | OPD0010 |
| P3Z22V10-DDH                       | Thailand      | SOT355-1 | XCR22LV10-10VO24C                 | Korea                 | Philippines             | OPD0011 |
| P3Z22V10IBA                        | Korea         | SOT261-3 | XCR22LV10-15PC28I                 | Philippines           |                         | OPC0001 |
| P3Z22V10IBD                        | Thailand      | SOT137-1 | XCR22LV10-15SO24I                 | Korea                 | Philippines             | OPD0010 |
| P3Z22V10IBDH                       | Thailand      | SOT355-1 | XCR22LV10-15VO24I                 | Korea                 | Philippines             | OPD0011 |
| P5Z22V10-7A                        | Korea         | SOT261-3 | XCR22V10-7PC28C                   | Philippines           |                         | OPC0001 |
| P5Z22V10-7D                        | Thailand      | SOT137-1 | XCR22V10-7SO24C                   | Korea                 | Philippines             | OPD0010 |
| P5Z22V10-7DH                       | Thailand      | SOT355-1 | XCR22V10-7VO24C                   | Korea                 | Philippines             | OPD0011 |
| P5Z22V10-DA                        | Korea         | SOT261-3 | XCR22V10-10PC28C                  | Philippines           |                         | OPC0001 |
| P5Z22V10-DD                        | Thailand      | SOT137-1 | XCR22V10-10SO24C                  | Korea                 | Philippines             | OPD0010 |
| P5Z22V10-DDH                       | Thailand      | SOT355-1 | XCR22V10-10VO24C                  | Korea                 | Philippines             | OPD0011 |
| P5Z22V10IDA                        | Korea         | SOT261-3 | XCR22V10-10PC28I                  | Philippines           |                         | OPC0001 |
| P5Z22V10IDD                        | Thailand      | SOT137-1 | XCR22V10-10SO24I                  | Korea                 | Philippines             | OPD0010 |
| P5Z22V10IDDH                       | Thailand      | SOT355-1 | XCR22V10-10VO24I                  | Korea                 | Philippines             | OPD0011 |
| PZ3032-10A44                       | Korea         | SOT187-2 | XCR3032-10PC44C                   | Korea                 | Philippines             | OPC0005 |
| PZ3032-10BC                        | Taiwan        | SOT376-1 | XCR3032-10VQ44C                   | Korea                 | Philippines             | OPQ0017 |
| PZ3032-12A44                       | Korea         | SOT187-2 | XCR3032-12PC44C                   | Korea                 | Philippines             | OPC0005 |
| PZ3032-12BC                        | Taiwan        | SOT376-1 | XCR3032-12VQ44C                   | Korea                 | Philippines             | OPQ0017 |
| PZ3032-8A44                        | Korea         | SOT187-2 | XCR3032-8PC44C                    | Korea                 | Philippines             | OPC0005 |
| PZ3032-8BC                         | Taiwan        | SOT376-1 | XCR3032-8VQ44C                    | Korea                 | Philippines             | OPQ0017 |
| PZ3032AS10A44                      | Taiwan        | SOT187-2 | XCR3032A-10PC44C                  | Korea                 | Philippines             | OPC0005 |
| PZ3032AS10BC                       | Taiwan        | SOT376-1 | XCR3032A-10VQ44C                  | Korea                 | Philippines             | OPQ0017 |
| PZ3032AS6A44                       | Taiwan        | SOT187-2 | XCR3032A-6PC44C                   | Korea                 | Philippines             | OPC0005 |
| PZ3032AS6BC                        | Taiwan        | SOT376-1 | XCR3032A-6VQ44C                   | Korea                 | Philippines             | OPQ0017 |
| PZ3032AS7A44                       | Taiwan        | SOT187-2 | XCR3032A-7PC44C                   | Korea                 | Philippines             | OPC0005 |
| PZ3032AS7BC                        | Taiwan        | SOT376-1 | XCR3032A-7VQ44C                   | Korea                 | Philippines             | OPQ0017 |
| PZ3032CS10A44                      | Korea         | SOT187-2 | XCR3032C-10PQ44C                  | Korea                 | Philippines             | OPC0005 |
| PZ3032CS10BC                       | Taiwan        | SOT376-1 | XCR3032C-10VQ44C                  | Korea                 | Philippines             | OPQ0017 |
| PZ3032CS12A44                      | Korea         | SOT187-2 | XCR3032C-12PC44C                  | Korea                 | Philippines             | OPC0005 |
| PZ3032CS12BC                       | Taiwan        | SOT376-1 | XCR3032C-12VQ44C                  | Korea                 | Philippines             | OPQ0017 |
| PZ3032CS8A44                       | Korea         | SOT187-2 | XCR3032C-8PC44C                   | Korea                 | Philippines             | OPC0005 |
| PZ3032CS8BC                        | Taiwan        | SOT376-1 | XCR3032C-8VQ44C                   | Korea                 | Philippines             | OPQ0017 |
| PZ3032DS10A44                      | Taiwan        | SOT187-2 | XCR3032A-10PC44I                  | Korea                 | Philippines             | OPC0005 |
| PZ3032DS10BC                       | Taiwan        | SOT376-1 | XCR3032A-10VQ44I                  | Korea                 | Philippines             | OPQ0017 |
| PZ3032DS7A44                       | Taiwan        | SOT187-2 | XCR3032A-7PC44I                   | Korea                 | Philippines             | OPC0005 |
| PZ3032DS7BC                        | Taiwan        | SOT376-1 | XCR3032A-7VQ44I                   | Korea                 | Philippines             | OPQ0017 |
| PZ3032I10A44                       | Korea         | SOT187-2 | XCR3032-10PC44I                   | Korea                 | Philippines             | OPC0005 |
| PZ3032I10BC                        | Taiwan        | SOT376-1 | XCR3032-10VQ44I                   | Korea                 | Philippines             | OPQ0017 |
| PZ3032I12A44                       | Korea         | SOT187-2 | XCR3032-12PC44I                   | Korea                 | Philippines             | OPC0005 |
| PZ3032I12BC                        | Taiwan        | SOT376-1 | XCR3032-12VQ44I                   | Korea                 | Philippines             | OPQ0017 |
| PZ3032NS10A44                      | Korea         | SOT187-2 | XCR3032C-10PC44I                  | Korea                 | Philippines             | OPC0005 |
| PZ3032NS10BC                       | Taiwan        | SOT376-1 | XCR3032C-10VQ44I                  | Korea                 | Philippines             | OPQ0017 |
| PZ3032NS12A44                      | Korea         | SOT187-2 | XCR3032C-12PC44I                  | Korea                 | Philippines             | OPC0005 |
| PZ3032NS12BC                       | Taiwan        | SOT376-1 | XCR3032C-12VQ44I                  | Korea                 | Philippines             | OPQ0017 |
| PZ3064-10A44                       | Korea         | SOT187-2 | XCR3064-10PC44C                   | Korea                 | Philippines             | OPC0005 |
| PZ3064-10A68                       | Korea         | SOT188-3 | XCR3064-10PC68C                   | Korea                 |                         | OPC0001 |

|               |           |          |                   |       |             |         |
|---------------|-----------|----------|-------------------|-------|-------------|---------|
| PZ3064-10A84  | Korea     | SOT189-3 | XCR3064-10PC84C   | Korea |             | OPC0001 |
| PZ3064-10BB1  | Hong Kong | SOT382-1 | XCR3064-10PQ100C  | Korea | Philippines | OPQ0013 |
| PZ3064-10BC   | Taiwan    | SOT376-1 | XCR3064-10VQ44C   | Korea | Philippines | OPQ0017 |
| PZ3064-12A44  | Korea     | SOT187-2 | XCR3064-12PC44C   | Korea | Philippines | OPC0005 |
| PZ3064-12A68  | Korea     | SOT188-3 | XCR3064-12PC68C   | Korea |             | OPC0001 |
| PZ3064-12A84  | Korea     | SOT189-3 | XCR3064-12PC84C   | Korea |             | OPC0001 |
| PZ3064-12BB1  | Hong Kong | SOT382-1 | XCR3064-12PQ100C  | Korea | Philippines | OPQ0013 |
| PZ3064-12BC   | Taiwan    | SOT376-1 | XCR3064-12VQ44C   | Korea | Philippines | OPQ0017 |
| PZ3064AS10A44 | Taiwan    | SOT187-2 | XCR3064A-10PC44C  | Korea | Philippines | OPC0005 |
| PZ3064AS10BC  | Taiwan    | SOT376-1 | XCR3064A-10VQ44C  | Korea | Philippines | OPQ0017 |
| PZ3064AS10BP  | Taiwan    | SOT386-1 | XCR3064A-10VQ100C | Korea | Philippines | OPQ0012 |
| PZ3064AS7A44  | Taiwan    | SOT187-2 | XCR3064A-7PC44C   | Korea | Philippines | OPC0005 |
| PZ3064AS7BC   | Taiwan    | SOT376-1 | XCR3064A-7VQ44C   | Korea | Philippines | OPQ0017 |
| PZ3064AS7BP   | Taiwan    | SOT386-1 | XCR3064A-7VQ100C  | Korea | Philippines | OPQ0012 |
| PZ3064DS10A44 | Taiwan    | SOT187-2 | XCR3064A-12VQ44I  | Korea | Philippines | OPC0005 |
| PZ3064DS10BC  | Taiwan    | SOT376-1 | XCR3064A-10VQ44I  | Korea | Philippines | OPQ0017 |
| PZ3064DS10BP  | Taiwan    | SOT386-1 | XCR3064A-10VQ100I | Korea | Philippines | OPQ0012 |
| PZ3064DS12A44 | Taiwan    | SOT187-2 | XCR3064A-12PC44I  | Korea | Philippines | OPC0005 |
| PZ3064DS12BC  | Taiwan    | SOT376-1 | XCR3064A-12VQ44I  | Korea | Philippines | OPQ0017 |
| PZ3064DS12BP  | Taiwan    | SOT386-1 | XCR3064A-12VQ100I | Korea | Philippines | OPQ0012 |
| PZ3064I12A44  | Korea     | SOT187-2 | XCR3064-12PC44I   | Korea | Philippines | OPC0005 |
| PZ3064I12A68  | Korea     | SOT188-3 | XCR3064-12PC68I   | Korea |             | OPC0001 |
| PZ3064I12A84  | Korea     | SOT189-3 | XCR3064-12PC84I   | Korea |             | OPC0001 |
| PZ3064I12BB1  | Hong Kong | SOT382-1 | XCR3064-12PQ100I  | Korea | Philippines | OPQ0013 |
| PZ3064I12BC   | Taiwan    | SOT376-1 | XCR3064-12VQ44I   | Korea | Philippines | OPQ0017 |
| PZ3064I15A44  | Korea     | SOT187-2 | XCR3064-15PC44I   | Korea | Philippines | OPC0005 |
| PZ3064I15A68  | Korea     | SOT188-3 | XCR3064-15PC68I   | Korea |             | OPC0001 |
| PZ3064I15A84  | Korea     | SOT189-3 | XCR3064-15PC84I   | Korea |             | OPC0001 |
| PZ3064I15BB1  | Hong Kong | SOT382-1 | XCR3064-15PQ100I  | Korea | Philippines | OPQ0013 |
| PZ3064I15BC   | Taiwan    | SOT376-1 | XCR3064-15VQ44I   | Korea | Philippines | OPQ0017 |
|               |           |          |                   |       |             |         |
| PZ3128AS10BE  | Taiwan    | SOT425-1 | XCR3128A-10TQ128C | Korea |             | OPQ0028 |
| PZ3128AS10BP  | Taiwan    | SOT386-1 | XCR3128A-10VQ100C | Korea | Philippines | OPQ0012 |
| PZ3128AS12BE  | Taiwan    | SOT425-1 | XCR3128A-12TQ128C | Korea |             | OPQ0028 |
| PZ3128AS12BP  | Taiwan    | SOT386-1 | XCR3128A-12VQ100C | Korea | Philippines | OPQ0012 |
| PZ3128AS7BE   | Taiwan    | SOT425-1 | XCR3128A-7TQ128C  | Korea |             | OPQ0028 |
| PZ3128AS7BP   | Taiwan    | SOT386-1 | XCR3128A-7VQ100C  | Korea | Philippines | OPQ0012 |
| PZ3128DS10BE  | Taiwan    | SOT425-1 | XCR3128A-10TQ128I | Korea |             | OPQ0028 |
| PZ3128DS10BP  | Taiwan    | SOT386-1 | XCR3128A-10VQ100I | Korea | Philippines | OPQ0012 |
| PZ3128DS15BE  | Taiwan    | SOT425-1 | XCR3128A-15TQ128I | Korea |             | OPQ0028 |
| PZ3128DS15BP  | Taiwan    | SOT386-1 | XCR3128A-15VQ100I | Korea | Philippines | OPQ0012 |
| PZ3128IS12A84 | Korea     | SOT189-3 | XCR3128-12PC84I   | Korea |             | OPC0001 |
| PZ3128IS12BB1 | Hong Kong | SOT382-1 | XCR3128-12PQ100I  | Korea | Philippines | OPQ0013 |
| PZ3128IS12BB2 | Taiwan    | SOT322-2 | XCR3128-12PQ160I  | Korea | Philippines | OPQ0002 |
| PZ3128IS12BE  | Taiwan    | SOT425-1 | XCR3128-12TQ128I  | Korea |             | OPQ0028 |
| PZ3128IS12BP  | Taiwan    | SOT386-1 | XCR3128-12VQ100I  | Korea | Philippines | OPQ0012 |
| PZ3128IS15A84 | Korea     | SOT189-3 | XCR3128-15PC84I   | Korea |             | OPC0001 |
| PZ3128IS15BB1 | Hong Kong | SOT382-1 | XCR3128-15PQ100I  | Korea | Philippines | OPQ0013 |
| PZ3128IS15BB2 | Taiwan    | SOT322-2 | XCR3128-15PQ160I  | Korea | Philippines | OPQ0002 |
| PZ3128IS15BE  | Taiwan    | SOT425-1 | XCR3128-15TQ128I  | Korea |             | OPQ0028 |
| PZ3128IS15BP  | Taiwan    | SOT386-1 | XCR3128-15VQ100I  | Korea | Philippines | OPQ0012 |
| PZ3128-S10A84 | Korea     | SOT189-3 | XCR3128-10PC84C   | Korea |             | OPC0001 |
| PZ3128-S10BB1 | Hong Kong | SOT382-1 | XCR3128-10PQ100C  | Korea | Philippines | OPQ0013 |
| PZ3128-S10BB2 | Taiwan    | SOT322-2 | XCR3128-10PQ160C  | Korea | Philippines | OPQ0002 |
| PZ3128-S10BE  | Taiwan    | SOT425-1 | XCR3128-10TQ128C  | Korea |             | OPQ0028 |
| PZ3128-S10BP  | Taiwan    | SOT386-1 | XCR3128-10VQ100C  | Korea | Philippines | OPQ0012 |
| PZ3128-S12A84 | Korea     | SOT189-3 | XCR3128-12PC84C   | Korea |             | OPC0001 |
| PZ3128-S12BB1 | Hong Kong | SOT382-1 | XCR3128-12PQ100C  | Korea | Philippines | OPQ0013 |
| PZ3128-S12BB2 | Taiwan    | SOT322-2 | XCR3128-12PQ160C  | Korea | Philippines | OPQ0002 |
| PZ3128-S12BE  | Taiwan    | SOT425-1 | XCR3128-12TQ128C  | Korea |             | OPQ0028 |
| PZ3128-S12BP  | Taiwan    | SOT386-1 | XCR3128-12VQ100C  | Korea | Philippines | OPQ0012 |
| PZ3128-S15A84 | Korea     | SOT189-3 | XCR3128-15PC84C   | Korea |             | OPC0001 |
| PZ3128-S15BB1 | Hong Kong | SOT382-1 | XCR3128-15PQ100C  | Korea | Philippines | OPQ0013 |
| PZ3128-S15BB2 | Taiwan    | SOT322-2 | XCR3128-15PQ160C  | Korea | Philippines | OPQ0002 |
| PZ3128-S15BE  | Taiwan    | SOT425-1 | XCR3128-15TQ128C  | Korea |             | OPQ0028 |
| PZ3128-S15BP  | Taiwan    | SOT386-1 | XCR3128-15VQ100C  | Korea | Philippines | OPQ0012 |

|               |           |          |                   |       |             |         |
|---------------|-----------|----------|-------------------|-------|-------------|---------|
| PZ3320C10BE   | Korea     | SOT435-1 | XCR3320-10TQ160C  | Korea |             | OPQ0029 |
| PZ3320C10EB   | Korea     | SOT471-1 | XCR3320-10BG256C  | Korea |             | OBG0021 |
| PZ3320C7BE    | Korea     | SOT435-1 | XCR3320-7TQ160C   | Korea |             | OPQ0029 |
| PZ3320C7EB    | Korea     | SOT471-1 | XCR3320-7BG256C   | Korea |             | OBG0021 |
| PZ3320N8BE    | Korea     | SOT435-1 | XCR3320-8TQ160I   | Korea |             | OPQ0029 |
| PZ3320N8EB    | Korea     | SOT471-1 | XCR3320-8BG256I   | Korea |             | OBG0021 |
|               |           |          |                   |       |             |         |
| PZ3960C7EB    | Korea     | SOT514-1 | XCR3960-7BG492C   | Korea |             | OBG0026 |
| PZ3960N8EB    | Korea     | SOT514-1 | XCR3960-8BG492I   | Korea |             | OBG0026 |
|               |           |          |                   |       |             |         |
| PZ5032-10A44  | Korea     | SOT187-2 | XCR5032-10PC44C   | Korea | Philippines | OPC0005 |
| PZ5032-10BC   | Taiwan    | SOT376-1 | XCR5032-10VQ44C   | Korea | Philippines | OPQ0017 |
| PZ5032-6A44   | Korea     | SOT187-2 | XCR5032-6PC44C    | Korea | Philippines | OPC0005 |
| PZ5032-6BC    | Taiwan    | SOT376-1 | XCR5032-6VQ44C    | Korea | Philippines | OPQ0017 |
| PZ5032-7A44   | Korea     | SOT187-2 | XCR5032-7PC44C    | Korea | Philippines | OPC0005 |
| PZ5032-7BC    | Taiwan    | SOT376-1 | XCR5032-7VQ44C    | Korea | Philippines | OPQ0017 |
| PZ5032CS10A44 | Korea     | SOT187-2 | XCR5032C-10PC44C  | Korea | Philippines | OPC0005 |
| PZ5032CS10BC  | Taiwan    | SOT376-1 | XCR5032C-10VQ44C  | Korea | Philippines | OPQ0017 |
| PZ5032CS6A44  | Korea     | SOT187-2 | XCR5032C-6PC44C   | Korea | Philippines | OPC0005 |
| PZ5032CS6BC   | Taiwan    | SOT376-1 | XCR5032C-6VQ44C   | Korea | Philippines | OPQ0017 |
| PZ5032CS7A44  | Korea     | SOT187-2 | XCR5032C-7PC44C   | Korea | Philippines | OPC0005 |
| PZ5032CS7BC   | Taiwan    | SOT376-1 | XCR5032C-7VQ44C   | Korea | Philippines | OPQ0017 |
| PZ5032I10A44  | Korea     | SOT187-2 | XCR5032-10PC44I   | Korea | Philippines | OPC0005 |
| PZ5032I10BC   | Taiwan    | SOT376-1 | XCR5032-10VQ44I   | Korea | Philippines | OPQ0017 |
| PZ5032I7A44   | Korea     | SOT187-2 | XCR5032-7PC44I    | Korea | Philippines | OPC0005 |
| PZ5032I7BC    | Taiwan    | SOT376-1 | XCR5032-7VQ44I    | Korea | Philippines | OPQ0017 |
| PZ5032NS10A44 | Korea     | SOT187-2 | XCR5032C-10PC44I  | Korea | Philippines | OPC0005 |
| PZ5032NS10BC  | Taiwan    | SOT376-1 | XCR5032C-10VQ44I  | Korea | Philippines | OPQ0017 |
| PZ5032NS7A44  | Korea     | SOT187-2 | XCR5032C-7PC44I   | Korea | Philippines | OPC0005 |
| PZ5032NS7BC   | Taiwan    | SOT376-1 | XCR5032C-7VQ44I   | Korea | Philippines | OPQ0017 |
|               |           |          |                   |       |             |         |
| PZ5064-10A44  | Korea     | SOT187-2 | XCR5064-10PC44C   | Korea | Philippines | OPC0005 |
| PZ5064-10A68  | Korea     | SOT188-3 | XCR5064-10PC68C   | Korea |             | OPC0001 |
| PZ5064-10A84  | Korea     | SOT189-3 | XCR5064-10PC84C   | Korea |             | OPC0001 |
| PZ5064-10BB1  | Hong Kong | SOT382-1 | XCR5064-10PQ100C  | Korea | Philippines | OPQ0013 |
| PZ5064-10BC   | Taiwan    | SOT376-1 | XCR5064-10VQ44C   | Korea | Philippines | OPQ0017 |
| PZ5064-7A44   | Korea     | SOT187-2 | XCR5064-7PC44C    | Korea | Philippines | OPC0005 |
| PZ5064-7A68   | Korea     | SOT188-3 | XCR5064-7PC68C    | Korea |             | OPC0001 |
| PZ5064-7A84   | Korea     | SOT189-3 | XCR5064-7PC84C    | Korea |             | OPC0001 |
| PZ5064-7BB1   | Hong Kong | SOT382-1 | XCR5064-7PQ100C   | Korea | Philippines | OPQ0013 |
| PZ5064-7BC    | Taiwan    | SOT376-1 | XCR5064-7VQ44C    | Korea | Philippines | OPQ0017 |
| PZ5064CS10A44 | Korea     | SOT187-2 | XCR5064C-10PC44C  | Korea | Philippines | OPC0005 |
| PZ5064CS10BC  | Taiwan    | SOT376-1 | XCR5064C-10VQ44C  | Korea | Philippines | OPQ0017 |
| PZ5064CS10BP  | Taiwan    | SOT386-1 | XCR5064C-10VQ100C | Korea | Philippines | OPQ0012 |
| PZ5064CS7A44  | Korea     | SOT187-2 | XCR5064C-7PC44C   | Korea | Philippines | OPC0005 |
| PZ5064CS7BC   | Taiwan    | SOT376-1 | XCR5064C-7VQ44C   | Korea | Philippines | OPQ0017 |
| PZ5064CS7BP   | Taiwan    | SOT386-1 | XCR5064C-7VQ100C  | Korea | Philippines | OPQ0012 |
| PZ5064I10A44  | Korea     | SOT187-2 | XCR5064-10PC44I   | Korea | Philippines | OPC0005 |
| PZ5064I10A68  | Korea     | SOT188-3 | XCR5064-10PC68I   | Korea |             | OPC0001 |
| PZ5064I10A84  | Korea     | SOT189-3 | XCR5064-10PC84I   | Korea |             | OPC0001 |
| PZ5064I10BB1  | Hong Kong | SOT382-1 | XCR5064-10PQ100I  | Korea | Philippines | OPQ0013 |
| PZ5064I10BC   | Taiwan    | SOT376-1 | XCR5064-10VQ44I   | Korea | Philippines | OPQ0017 |
| PZ5064I12A44  | Korea     | SOT187-2 | XCR5064-12PC44I   | Korea | Philippines | OPC0005 |
| PZ5064I12A68  | Korea     | SOT188-3 | XCR5064-12PC68I   | Korea |             | OPC0001 |
| PZ5064I12A84  | Korea     | SOT189-3 | XCR5064-12PC84I   | Korea |             | OPC0001 |
| PZ5064I12BB1  | Hong Kong | SOT382-1 | XCR5064-12PQ100I  | Korea | Philippines | OPQ0013 |
| PZ5064I12BC   | Taiwan    | SOT376-1 | XCR5064-12VQ44I   | Korea | Philippines | OPQ0017 |
| PZ5064NS10A44 | Korea     | SOT187-2 | XCR5064C-10PC44I  | Korea | Philippines | OPC0005 |
| PZ5064NS10BC  | Taiwan    | SOT376-1 | XCR5064C-10VQ44I  | Korea | Philippines | OPQ0017 |
| PZ5064NS10BP  | Taiwan    | SOT386-1 | XCR5064C-10VQ100I | Korea | Philippines | OPQ0012 |
| PZ5064NS12A44 | Korea     | SOT187-2 | XCR5064C-12PC44I  | Korea | Philippines | OPC0005 |
| PZ5064NS12BC  | Taiwan    | SOT376-1 | XCR5064C-12VQ44I  | Korea | Philippines | OPQ0017 |
| PZ5064NS12BP  | Taiwan    | SOT386-1 | XCR5064C-12VQ100I | Korea | Philippines | OPQ0012 |

|               |           |          |                   |       |             |         |
|---------------|-----------|----------|-------------------|-------|-------------|---------|
| PZ5128CS10BE  | Taiwan    | SOT425-1 | XCR5128C-10TQ128C | Korea |             | OPQ0028 |
| PZ5128CS10BP  | Taiwan    | SOT386-1 | XCR5128C-10VQ100C | Korea | Philippines | OPQ0012 |
| PZ5128CS12BE  | Taiwan    | SOT425-1 | XCR5128C-12TQ128C | Korea |             | OPQ0028 |
| PZ5128CS12BP  | Taiwan    | SOT386-1 | XCR5128C-12VQ100C | Korea | Philippines | OPQ0012 |
| PZ5128CS7BE   | Taiwan    | SOT425-1 | XCR5128C-7TQ128C  | Korea |             | OPQ0028 |
| PZ5128CS7BP   | Taiwan    | SOT386-1 | XCR5128C-7VQ100C  | Korea | Philippines | OPQ0012 |
| PZ5128IS10A84 | Korea     | SOT189-3 | XCR5128-10PC84I   | Korea |             | OPC0001 |
| PZ5128IS10BB1 | Hong Kong | SOT382-1 | XCR5128-10PQ100I  | Korea | Philippines | OPQ0013 |
| PZ5128IS10BB2 | Taiwan    | SOT322-2 | XCR5128-10PQ160I  | Korea | Philippines | OPQ0002 |
| PZ5128IS10BE  | Taiwan    | SOT425-1 | XCR5128-10TQ128I  | Korea |             | OPQ0028 |
| PZ5128IS10BP  | Taiwan    | SOT386-1 | XCR5128-10VQ100I  | Korea | Philippines | OPQ0012 |
| PZ5128IS15A84 | Korea     | SOT189-3 | XCR5128-15PC84I   | Korea |             | OPC0001 |
| PZ5128IS15BB1 | Hong Kong | SOT382-1 | XCR5128-15PQ100I  | Korea | Philippines | OPQ0013 |
| PZ5128IS15BB2 | Taiwan    | SOT322-2 | XCR5128-15PQ160I  | Korea | Philippines | OPQ0002 |
| PZ5128IS15BE  | Taiwan    | SOT425-1 | XCR5128-15TQ128I  | Korea |             | OPQ0028 |
| PZ5128IS15BP  | Taiwan    | SOT386-1 | XCR5128-15VQ100I  | Korea | Philippines | OPQ0012 |
| PZ5128NS10BE  | Taiwan    | SOT425-1 | XCR5128C-10TQ128I | Korea |             | OPQ0028 |
| PZ5128NS10BP  | Taiwan    | SOT386-1 | XCR5128C-10VQ100I | Korea | Philippines | OPQ0012 |
| PZ5128NS15BE  | Taiwan    | SOT425-1 | XCR5128C-15TQ128I | Korea |             | OPQ0028 |
| PZ5128NS15BP  | Taiwan    | SOT386-1 | XCR5128C-15VQ100I | Korea | Philippines | OPQ0012 |
| PZ5128-S10A84 | Korea     | SOT189-3 | XCR5128-10PC84C   | Korea |             | OPC0001 |
| PZ5128-S10BB1 | Hong Kong | SOT382-1 | XCR5128-10PQ100C  | Korea | Philippines | OPQ0013 |
| PZ5128-S10BB2 | Taiwan    | SOT322-2 | XCR5128-10PQ160C  | Korea | Philippines | OPQ0002 |
| PZ5128-S10BE  | Taiwan    | SOT425-1 | XCR5128-10TQ128C  | Korea |             | OPQ0028 |
| PZ5128-S10BP  | Taiwan    | SOT386-1 | XCR5128-10VQ100C  | Korea | Philippines | OPQ0012 |
| PZ5128-S12A84 | Korea     | SOT189-3 | XCR5128-12PC84C   | Korea |             | OPC0001 |
| PZ5128-S12BB1 | Hong Kong | SOT382-1 | XCR5128-12PQ100C  | Korea | Philippines | OPQ0013 |
| PZ5128-S12BB2 | Taiwan    | SOT322-2 | XCR5128-12PQ160C  | Korea | Philippines | OPQ0002 |
| PZ5128-S12BE  | Taiwan    | SOT425-1 | XCR5128-12TQ128C  | Korea |             | OPQ0028 |
| PZ5128-S12BP  | Taiwan    | SOT386-1 | XCR5128-12VQ100C  | Korea | Philippines | OPQ0012 |
| PZ5128-S7A84  | Korea     | SOT189-3 | XCR5128-7PC84C    | Korea |             | OPC0001 |
| PZ5128-S7BB1  | Hong Kong | SOT382-1 | XCR5128-7PQ100C   | Korea | Philippines | OPQ0013 |
| PZ5128-S7BB2  | Taiwan    | SOT322-2 | XCR5128-7PQ160C   | Korea | Philippines | OPQ0002 |
| PZ5128-S7BE   | Taiwan    | SOT425-1 | XCR5128-7TQ128C   | Korea |             | OPQ0028 |
| PZ5128-S7BP   | Taiwan    | SOT386-1 | XCR5128-7VQ100C   | Korea | Philippines | OPQ0012 |