

# PCN96008 Data

## Device Qualification Data

Product	Fab	Test	Lot	SS	Hours	Fails	Status
XC4005	Seiko	HTOL	X3668R	80	0	0	Continuing
XC4005	Seiko	HTOL	X3668R	80	168	0	Continuing
XC4005	Seiko	HTOL	X3668R	80	256	1	Continuing
XC4005	Seiko	HTOL	X3668R	79	500	0	Continuing
XC4005	Seiko	HTOL	X3668R	79	1000	0	<b>Complete</b>
XC4005	Seiko	HTOL	X3874R	76	0	0	Continuing
XC4005	Seiko	HTOL	X3874R	76	168	0	Continuing
XC4005	Seiko	HTOL	X3874R	76	256	0	Continuing
XC4005	Seiko	HTOL	X3874R	76	500	0	Continuing
XC4005	Seiko	HTOL	X3874R	76	1000	0	<b>Complete</b>
XC4013	Seiko	HTOL	X3927R	76	0	0	Continuing
XC4013	Seiko	HTOL	X3927R	76	168	0	Continuing
XC4013	Seiko	HTOL	X3927R	76	256	0	Continuing
XC4013	Seiko	HTOL	X3927R	76	500	0	Continuing
XC4013	Seiko	HTOL	X3927R	76	1000	0	<b>Complete</b>
XC4013	UMC	HTOL	X3757R	130	0	0	Continuing
XC4013	UMC	HTOL	X3757R	130	168	0	Continuing
XC4013	UMC	HTOL	X3757R	130	256	0	Continuing
XC4013	UMC	HTOL	X3757R	130	500	0	Continuing
XC4013	UMC	HTOL	X3757R	130	1000	0	<b>Complete</b>
XC4013	UMC	HTOL	X3763R	77	0	0	Continuing
XC4013	UMC	HTOL	X3763R	77	168	0	Continuing
XC4013	UMC	HTOL	X3763R	77	256	0	Continuing
XC4013	UMC	HTOL	X3763R	77	500	0	Continuing
XC4013	UMC	HTOL	X3763R	77	1000	0	<b>Complete</b>
XC4013	UMC	T/C	X3806R	76	0	0	Continuing
XC4013	UMC	T/C	X3806R	76	100	0	Continuing
XC4013	UMC	T/C	X3806R	76	200	0	Continuing
XC4013	UMC	T/C	X3806R	76	500	0	<b>Complete</b>
XC4013	UMC	85/85	X3787R	76	0	0	Continuing
XC4013	UMC	85/85	X3787R	76	168	0	Continuing
XC4013	UMC	85/85	X3787R	76	500	0	Continuing
XC4013	UMC	85/85	X3787R	76	1000	0	<b>Complete</b>
XC4025	UMC	HTOL	X3826R	77	0	0	Continuing
XC4025	UMC	HTOL	X3826R	77	168	0	Continuing
XC4025	UMC	HTOL	X3826R	77	256	0	Continuing

XC4025	UMC	HTOL	X3826R	77	500	0	Continuing
XC4025	UMC	HTOL	X3826R	77	1000	0	<b>Complete</b>
XC4025	UMC	T/C	X3826R	73	0	0	Continuing
XC4025	UMC	T/C	X3826R	73	100	0	Continuing
XC4025	UMC	T/C	X3826R	73	200	0	Continuing
XC4025	UMC	T/C	X3826R	73	500	0	<b>Complete</b>